NTSB ID: DEN02LA031 Aircraft Registration Number: N8SD

Occurrence Date: 03/10/2002 Most Critical Injury: None

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
Windsor	СО	80551	1110	MST	
Airport Proximity: Off Airport/Airstrip	Distance Fror	n Landing Facility:		Direction Fro	m Airport:

Aircraft Information Summary

All of all morniation Cammary										
Aircraft Manufacturer	Model/Series	Type of Aircraft								
Doyle	Kitfox III	Airplane								

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On March 10, 2002, approximately 1110 mountain standard time, a Doyle Kitfox III amateur-built airplane, N8SD, was substantially damaged when it nosed over during a forced landing near Windsor, Colorado. The private pilot and a passenger were not injured. Visual meteorological conditions prevailed, and no flight plan had been filed for the personal flight being conducted under Title 14 CFR (Code of Federal Regulations) Part 91. The flight originated at Greeley, Colorado, at 1045, and was en route to Loveland, Colorado.

According to the pilot's accident report, he was cruising at 800 feet above the ground when the engine lost power. He made a forced landing in a hay field. The tall grass caused the airplane to nose over, crushing the vertical stabilizer.

According to a statement made to the Weld County Sheriff's Office, the pilot indicated that "the engine stopped and the propeller also came to a complete stop." He also stated he was unsuccessful in attempting to restart the engine in flight.

Contacted after the accident, the pilot surmised "a fuel flow problem" had resulted in the loss of engine power.

NTSB ID: DEN02LA031

Occurrence Date: 03/10/2002

AVIATION	Occurrence Type: Accident											
Landing Facility/Approach Information	<u>'</u>											
Airport Name	,	Airport ID	D: /	Airport Eleva	tion MSL	Run	way Used	Runwa	y Lengt	h R	unway Width	
Runway Surface Type: Unknown										I		
Runway Surface Condition: Unknown												
Type Instrument Approach: Unknown												
VFR Approach/Landing: Forced Landing												
Aircraft Information												
Aircraft Manufacturer		del/Se							Number			
Doyle		Kit	tfox II	 					1001			
Airworthiness Certificate(s): Experimental (Special)												
Landing Gear Type: Tailwheel												
	Homebuilt Aircraft? Yes Number of Seats: 2						1050 LBS Numbe			r of Engi	nes: 1	
Engine Type: Reciprocating									Rated Power: 66 HP			
- Aircraft Inspection Information												
Type of Last Inspection		Date of Last Inspection Time Sin			nce Last Insp	ection		Airframe	Total Time			
Conditional		01/200)2					10 Ho	ours		380 Hours	
- Emergency Locator Transmitter (ELT) Information												
ELT Installed? ELT Operation	ted?				ELT	Aided i	n Locating Ac	cident S	ite?			
Owner/Operator Information												
Registered Aircraft Owner		Stree	et Ad	dress On File								
W. Scott Doyle		City									Zip Code	
		 								80526		
Operator of Aircraft		Stree	et Ado		Rea'	d Aircr	aft Owner					
Same as Reg'd Aircraft Owner		Same as Reg'd Aircraft Owner City						State	Zip Code			
Operator Does Business As:		_!	Operator Designator Code:									
- Type of U.S. Certificate(s) Held: None												
Air Carrier Operating Certificate(s):												
Operating Certificate:				Operator C	Certific	ate:						
Regulation Flight Conducted Under: Part 91: General	al Aviati	ion		1 '								
Type of Flight Operation Conducted: Personal												
	FACTI	JAL RE	POR'	T - AVIATI	ON						Page 2	

NTSB ID: DEN02LA031

Occurrence Date: 03/10/2002

AVIATION	Occurrence Type: Accident											
First Pilot Information								_				
Name					City				S	tate	Date of Birth	Age
On File					On File	n File On File On						53
Sex: M Seat Occupied: Left		Prin	cipal Profess	sion: Unkno	own Certificate Number: On File							
Certificate(s): Private												
Airplane Rating(s): Single-engine Land												
Rotorcraft/Glider/LTA: None												
Instrument Rating(s): None												
Instructor Rating(s): None												
Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review? 01/2001												
Medical Cert.: Class 3	aivers/li	m.		Date of	of Last N	Medical E	Exam: 06/2000					
•												
- Flight Time Matrix	A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Nigh	nt	I Actual	nstrument Simul	ated	Rotorcraft	Glider	Lighter Than Air
Total Time	450	350	450			6						
Pilot In Command(PIC)	450	350	450			6						
Instructor					-							
Last 90 Days	8	8	8		+							
Last 30 Days Last 24 Hours	2	2	2		+							
Seatbelt Used? Yes		der Harness			<u> </u> .	Toxico	logy Per	ormed? N	l	9	Eecond Pilot? No	
Ocalbeit Occur 1 Co	Siloui	uei Hairiess	Osea: 163			10/100	nogy i ci	omica: p	1 0		, coona i not.	,
Flight Plan/Itinerary												
Type of Flight Plan Filed: None												
Departure Point					T	State	Α	irport Ider	ntifier	Depa	arture Time	Time Zone
Greeley						СО		SXY		1045		MDT
Destination						State	A	irport Ider	ntifier			
Fort Collins						СО		NL				
Type of Clearance: None												
Type of Airspace: Class G												
Weather Information												
Source of Briefing: No record of	f briefir	ng										
Method of Briefing: Unknown												
			FACTUAL	REPORT	- AVIA	TION	1					Page 3

NTSB ID: DEN02LA031

Occurrence Date: 03/10/2002

Occurrence Type: Accident

	ETYBOR	Occurrenc	Occurrence Type: Accident										
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF Elevati	ion	WOF Di	stance Fr	om Acci	dent Site		Direction From Accident Site			
GXY	1115	MST	4658 Ft.	. MSL				15 NM	Mag.				
Sky/Lowes	st Cloud Condition: Clea				Ft.	AGL	Condition of Light: Day						
Lowest Ce	eiling: None		Ft.	AGL	Visib	ility:	10	SM	Altii	meter:	30.04	"Hg	
Temperatu	ure: 4 °C	Dew Point:	-5 °C	Wind	Direction:	100			Ft.				
Wind Spee	ed: 4	Gusts:		Weath	ner Condt	ions at Ac	cident S	ite: Visual C	Cond	itions			
Visibility (F	RVR): Ft.	. Visibility (R	VV)	SM	Intensity	y of Preci	oitation:						
Restriction	Restrictions to Visibility: None												
Type of Pro	ecipitation: None												
Accident	Information												
Aircraft Da	mage: Substantial		Aircraft Fire	e: None	ne Aircraft Exp					n None			
Classificati	ion: U.S. Registered/L	J.S. Soil											
- Injury Su	mmary Matrix	Fatal Se	erious Mino	or	None TOTAL								
First Pi	ilot				1		1						
Second	d Pilot						7						
Studen	nt Pilot						┨						
Flight I	Instructor	1					┫						
Check	Pilot						┨						
Flight E	Engineer												
Cabin /	Attendants												
Other 0							7						
Passer	ngers				1		1						
- TOTAL /	ABOARD -				2		2						
Other (<u> </u>					╗						
- GRANI	D TOTAL -	1			2		2						
			·										

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: DEN02LA031

Occurrence Date: 03/10/2002

Occurrence Type: Accident

Α	S	lm	in	ist	rat	ίv	e l	Ini	fο	rn	n۶	ati	O	n
,	10			ıυι	ıuı		U		\cdot		110	461	v	

Investigator-In-Charge (IIC)

Arnold W. Scott

Additional Persons Participating in This Accident/Incident Investigation:

Robert C Bunderson Air Safety Inspector - Airworthiness FAA - Flight Standards District Office 26805 E. 68th Ave #200 Denver, CO 80249